

FIG. 5




FIG. 6




FIG. 7







FIG 9



PROVIDE
SEPARATE
PARTS

PERFORATE
INTERIOR
SURFACES OF
SEPARATE
PARTS

DISPOSE
AT LEAST
ONE THER-
MAL ELE-
MENT IN
PARTS

FASTEN
PARTS TO-
GETHER
TO FORM
VAPORIZA-
TION
CHAMBER

Fig. 10d

FASTEN PARTS
TOGETHER TO
FORM VAP-
ORIZATION
CHAMBER

DISPOSE
AT LEAST ONE
THERMAL
ELEMENT IN
VAPORIZATION
CHAMBER

PROVIDE
SEPARATE
PARTS

CREATE
FISSURES/CRACKS/
IRREGULARITIES
IN INTERIOR
SURFACE OF
PARTS

DISPOSE AT
LEAST ONE
THERMAL
ELEMENT IN
PARTS

FASTEN PARTS
TOGETHER TO
FORM VAP-
ORIZATION
CHAMBER

Fig. 10e

FASTEN PARTS
TOGETHER
TO FORM
VAPORIZATION
CHAMBER

DISPOSE AT
LEAST ONE
THERMAL
ELEMENT IN
VAPORIZATION
CHAMBER